AOI Output	
Camtek	
B365133	
Bug Fix	Calculation of the inspection area during Camtek output, by using Auto Insp. Area, could be missing some exclusion areas between the blocks (with uPCB attribute allocated). These areas are marked as exclusion zones now.
CAD Output	
DPF, Save I	layer
BB03439	
Bug Fix	Importing some constructions in Gerber files using certain Ucam.properties conditions (always displaying the Options section in SmartStart) and saving the resulting layer as DPF file and using low output resolution could corrupt the saved DPF file. Loading these DPF file can be notifying for invalid aperture definitions and could be missing certain contour regions embedded in BLOck aperture (although editing the block aperture was correctly displaying the image). Importing the data and saving as DPF, using the indicated conditions, is not longer corrupting the data.
Gerber	
BB03475	
Bug Fix	Gerber output was not always respecting the rotation of some apertures. Issue was noticed, when generating Gerber output after importing an ODB++ layer containing the same aperture definition with a different rotation allocated. Both apertures were output into the same aperture definition (both with the same rotation). Issue was not noticed when saving the job after ODB++ import and reloading the saved job. Gerber output is now also defining the correct rotation when the output is generated directly after importing the ODB++ job.
XDPF	
BB03486	
Bug Fix	Running smartkleo script, for converting layers from an ODB++ job towards XDPF, could be running into memory problems (after running for hours, issue has been noticed on Linux platform). The conversion of this layer can be completed successful now.
Editing	
Apertures	
B364680	
Bug Fix	Loading Apertures from a DPF file that contains also True Objects was causing Ucam crash. The TrueObjects are ignored while loading apertures from an external file.
B365139	
Bug Fix	Group Pos/Neg is now preserving the Object attributes that were allocated to the original objects, previously these objects attributes could be lost after grouping.
B365363	
Bug Fix	Selecting a different aperture in the ApertureManager, while running Insert Flash, was still adding a flash with the previous active aperture instead of using the newly selected active aperture. The following flashes were using the current active aperture. Each newly added flash is using the actual active aperture, also after changing the active aperture.
BB03490	
Bug Fix	Generating a COMplex aperture from selected objects could be storing the net information, stored on the selected objects inside the definition of the COMplex aperture, loading these COMplex apertures was failing with the indication on illegal DPF syntax. Since net information inside an aperture definition is useless this is not longer stored inside the COMplex aperture. The net information stored inside a COMplex aperture is ignored while loading a DPF file, which ending a DPF file.
Enhanced F	ditor
BR02441	
Bug Fiv	Deleting the redundant segments of a crossing track and arc connection was
Buy FIX	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5

		not always calculating the exact same connection point between the track and arc, as a result a different rout group could be allocated to these objects. The remaining segments are now having the same end points.
In	sert	
BB	03523	
Bu	g Fix	Inserting a flash with a BLOck aperture was not pre-viewing the contour regions embedded in the block aperture definition. Also the regions are now highlighted while dragging the location to flash a block.
Tr	ansform	
В3	64960, B3650	59
Bu	g Fix	Transform Thicken, with option Straight, on the contour could be losing a clearance. Issue has been noticed on a cut-in clearance for which the cut-in lines are creating a small gap in the region, these cut-in lines are not coincident. Thickening these regions is preserving these clearances (in case the applied value is not justifying that the clearance should disappear).
BB	03336	
Bu	g Fix	Choking a contour, by using option Rounded and very small value for contourize.analytic.arc.expand.margin (issue has been noticed with contourize.analytic.arc.expand.margin: 0.0002mm) could be adding "bubble" at the edge of the choked region. Also Fill Vector could be suffering with the issue (when using similar configurations). Choking and Fill Vector are not suffering with these small configurations of contourize.analytic.arc.expand.margin.
Editin	g Tools	
BB	03527	
Bu	g Fix	A Java NullPointerException could be generated while clicking on Edit in the Draw Slots menu. The Java exception has been corrected while running the function.
Co	ontours	
B3	64764, B36498	39
Bu	g Fix	Exact Contourize could be failing with the notification of out of memory, this has been noticed on layers with many painted areas. Contourize has been improved for supporting these layers.
BB	03408	
Bu	g Fix	Contour merge, with option Single, on selected objects could change the image, disappearing of not selected regions has been noticed on certain constructions. Merging these objects is not longer influencing the objects that were not selected.
BB	03496	
Bu	g Fix	Exact Contourize could introduce ambiguous contours, by creating overlapping inner contours. This could result in situations where some inner contours were not correctly displayed. Exact Contourize is not longer generating these ambiguous configurations.
BB	03525	
Bu	g Fix	Exact Contourize of data far away from the origin (several meter) could be hanging. Issue was noticed while handling a layer resulting from importing a DXF file. These constructions can be contourized normally now.
BB	03544	
Bu	g Fix	Merging regions, defined in different CONtour aperture, when running the function on selected regions, could be losing a clearance. When merging on all objects and without any selections the image remained unchanged. Merging with or without selections is now preserving the image.
Fil	II Pattern	

Bug FixFill Pattern selecting option Fill With Tracks was not always respecting the
edges of the original contour region. Some tracks of the pattern could be
missing and other tracks could exceed the edge of the original image. Fill
Pattern behaves normally again.

Fill Vector

BB03447

BB03431

After running Fill Vector on selected contour regions all vectors, resulting from filling the regions, are now selected. Previously some objects were not selected.

Rout

Bug Fix

B364829	
Bug Fix	Running some functions in the Tools section of the Rout Manager was losing the current active aperture, a Warning message "no current aperture" was popping up after running the functions. These functions are now keeping the current aperture active.
BB03460	
Bug Fix	Using the Trim function, in Rout Manager, for connecting a track with an arc, could corrupt the image. Trim is now correctly connecting these objects.
BB03464	
Bug Fix	Running Default Order, in the Tools section of Rout Manager, after clearing the unused apertures, could be causing a Java NullPointerException. This exception has been resolved.
Shave	
B364432	
Bug Fix	Shaving Pad Track/Arc, by using option Reverse, was not respecting the requested clearance between the objects, the resulting clearance was slightly bigger than the indicate value. The CONtour region, used for shaving has been corrected for respecting the requested clearance.
B364942	
Bug Fix	Pad Shave was causing Ucam crash on certain constructions. Crash has been resolved.
ectrical Test	

Ele ctrical

Utest	
B364662	
Bug Fix	Test Point generation with activating option "Filter Copper Area's" could filter away all test points of certain nets, when all potential test points are embedded in a copper plane at one side. At least one test point remains on these jobs.
BB03455	
Bug Fix	The performance of calculating test points on painted pads was suffering with big areas in the mask layer(s), this has been notice on mask layers for which the enclosing box of the connected areas are covering a big part of the job. These mask layers are not longer delaying the calculation of the test points.

Input

Gerber	
B365381	
Bug Fix	Gerber input of a region with self-intersecting cut-in lines could be missing some of the connected cut-in clearances. These constructions are now flagged as self-intersecting contour and the clearance(s) get displayed.
BB03442	
Bug Fix	Gerber input of an almost full arc, with endpoints very close to each other, could result in a short track between the endpoints of the object. Issue was noticed after the conversion of a Gerber file that was created in high accuracy (5.5 mm) and with an almost full arc with 0.6μ between the endpoints of the arc. These arcs are now converted as expected.
BB03473	
Bug Fix	Gerber input of constructions containing self-intersecting contours could be missing some clearances (created by the self-intersecting cut-in lines). These constructions are now flagged and result in ambiguous contours (since cleaning up these contours can lose these clearances).
Import Eagle	
BB03520	
Bug Fix	Ucam could crash while importing certain Eagle files. These files can be loaded successfully now.
Import IPC-D	-356B
B363691, B36443	38
Bug Fix	Import of an IPC-D-356B files was always converting the file as it was created with 0.1 MIL values, Parameter record UNIT was ignored. The UNIT parameter is now correctly interpreted, even in case the alignment on the

Bug Fix	lug	Fix		
---------	-----	-----	--	--

parameter is now correctly interpreted, even in case the alignment on the line is conflicting with the IPC-D-356B specifications (in case of conflict a warning message is given but specified unit is considered).

Import ODB++

B364249	
Bug Fix	ODB++ Import of a job containing a rout layer for which the START_NAME and END_NAME parameters are not specified in the matrix file failed with a Java NullPointerException. These jobs can be imported successfully now.
B365307	
Bug Fix	The <resize_factor> defined on ODB++ features is now correctly applied. Previously the <resize_factor> on the negative objects was interpreted incorrectly.</resize_factor></resize_factor>
BB03437	
Bug Fix	ODB++ Import of job composed by nested symbol definitions (symbol definition using another symbol definition) on which transformations (mirror and rotation) are applied at different levels, could be applying the transformation in different sequence. These transformations are now applied in the same sequence as defined on the features, which results in the expected image.
BB03474, B3653	62
Bug Fix	The import of some compressed ODB++ jobs failed because the decompressing failed on long folder names. Decompressing these files by using 7z.exe allows importing these jobs. Configuration of external.decompress allows indicating which tool should be used for decompressing the TGZ files.
IPC-D-356	
B364826	
Bug Fix	Importing an IPC-D-356A file, for creating netlist reference layers, was creating all netlist reference points in case the IPC file is loaded in an empty or in a job that contains the same amount of layers as indicated in the IPC file (access field in the record definitions). In other situations some references could be missing. All netlist references are created from an IPC-D-356A file, independent from the amount of layers that are available in the iob when converting the IPC file.
SUM 3000	In the Job when converting the FC file.
BB03478	
Bug Fix	Applying the rout track compensation on small arcs, while loading a rout file, could result in invalid arcs. The compensated arcs are now valid.
Netlist Output	
IPC-ATG	
BB03459	
Bug Fix	Output Netlist ATG-IPC was only working on stepped data, output of flat
	data resulted in an empty file. Now IPC-ATG output also supports flat data.
IPC-D-356A	
B364857 Bug Fix	IPC-D-356A output, using the FixGenius algorithm (ipcmet.new_output_algorithm: 1), of a single layer job, which contains stepped data (blocks), and configuring ipc356a*style: ATG, is also adding the Soldermask flag (columns 73-74) for the records describing the drill holes (017 records). This S2 indication was missing for the 017 records.
Panelization	
BB03524	
Bug Fix	PanelPlus, by using an Outline layer containing chained tracks with an aperture (not a contour aperture), was creating a (reverse) contour aperture which was not cleaning the background (venting pattern) as expected. These reverse contours are now covering the background again.
Bug Fix PanelPlus	PanelPlus, by using an Outline layer containing chained tracks with an aperture (not a contour aperture), was creating a (reverse) contour aperture which was not cleaning the background (venting pattern) as expected. These reverse contours are now covering the background again.
Bug Fix PanelPlus B365405	PanelPlus, by using an Outline layer containing chained tracks with an aperture (not a contour aperture), was creating a (reverse) contour aperture which was not cleaning the background (venting pattern) as expected. These reverse contours are now covering the background again.
Bug Fix PanelPlus B365405 Bug Fix	PanelPlus, by using an Outline layer containing chained tracks with an aperture (not a contour aperture), was creating a (reverse) contour aperture which was not cleaning the background (venting pattern) as expected. These reverse contours are now covering the background again. PanelPlus, by using an Outline layer containing overlapping regions in different BLOck, was merging the different regions in the same (reverse) contour aperture (for cleaning the background, venting pattern), as a result inner contours could be created (and the background pattern became visible through these inner contours). These inner contours are no longer generated.

Bug Fix	Running PanelPlus by using an Outline layer containing the region (using a CONtour aperture) that is embedded in a BLOck aperture (array data) is now clearing the background (venting pattern) at the location of the stepped image. This was already the case when the region of the outline layer is not embedded in a BLOck aperture.
StepRepeat R	econstructor
BB03482	
Bug Fix	A crash, while running StepRepeat Reconstructor, has been resolved.
PowerRIP	
mlfdpf	
BB03510	
Bug Fix	Submitting a layer containing aperture attributes, for which a name starts with a dot, can cause failed processing of the data on the RIP. The aperture attributes are skipped from the DPF file.
SmartKleo	
BB03448	
Bug Fix	Running smartkleo script, for converting Gerber file towards XDPF, could be crashing (crash noticed on Linux platform). The conversion of this Gerber file can be completed successful again.
SmartPlot	
B364800	
Bug Fix	Submitting certain constructions from SmartPlot Merge Queue in SmartPlot Plot Queue could be losing certain regions. This has been noticed on layer for which the operator was notified for Open contours while submitting in the Plot Queue. These jobs are now correctly submitted towards the RIP.
B365629	
Bug Fix	TRIP is having issues while exposing some arcs, some very small arcs can be exposed as full circle and some other arcs can be exposed by a flash in its start and end point. These arcs are now expanded in tracks, while submitting from SmartPlot Merge Queue into Plot Queue.
BB03499	Cubraitting a lower to a platter with a TDID (Univ DID) aculd be loging contain
Bug Fix	inner contours of embedded outer contours (outer contour that is embedded inside an inner contour of the same CONtour aperture definition). SmartPlot is reviewing the construction of the regions for preventing embedded outer contours in the data provided to the TRIP.
BB03532	
Bug Fix	Submitting a layer, containing COMplex apertures with hole(s), from SmartPlot Merge Queue into Plot Queue of a TRIP could be causing a crash. These layers can submitted successfully now.
Verification	
Arcs & Draws	
B364962	
Bug Fix	Validating arcs, with an aperture, is preserve the object attributes that are stored on the original invalid arc(s). Previously these object attributes were lost on the validated arc objects.
BB03494	
Bug Fix	Arc validation could be validating a small slightly invalid arc into an almost full circle. Validating these arcs is only slightly changing the image, if appropriate a short arc will be replaced by a short track.
Copper Repair	r
B364028	
Bug Fix	DRC repair could corrupt the image, by removing track, while solving clearance violation between tracks flash on which multiple violations are found. These violation can be repaired without corrupting the construction.
Design Rules B364505	

Bug Fix	Running Design Rules Check could be missing some Peelable violations when running the verification with actual units set to MIL. The same violations are now found independent on the actual unit.
View	
BB03456	
Bug Fix	Some single arcs could be displayed as composed by different objects, this could be noticed when selecting, querying or displaying in Skeleton mode. These arcs are displayed normally again.
Apertures	
BB03521	
Bug Fix	A block aperture, on which as scale factor is defined, could ignore the scaling on donut shape objects, issue noticed on region composed by 2 full circles (outer and inner contour). These objects are correctly displayed nov
Select	
BB03445	
Bug Fix	Select Embedded could be selecting objects which would change the image after deleting these "embedded" objects. Issue has been noticed on selected COMplex apertures for which the outline is completely embedded CONtour region and the region has an inner contour inside the image of th COMplex aperture. These not full embedded objects are not longer selected as embedded objects.
Zoom	
BB03465	
Bug Fix	Sometimes some tracks were not displayed in Filled mode, these tracks are displayed again.
BB03522	
Bug Fix	Zoom In at certain objects (issue noticed while zooming in very deep on a rounded BOX aperture) could be causing an Ucam crash. Ucam is not longe crashing while zooming on these objects.